XT501 & X3300W MK2
Tracer Engineer mode setting

LED meaning:

🔴 Red light for selection of setting mode

🟢 Green light for selection parameter of mode

Example:

🔴🔴 = Red light blink twice, it is "Mode 2"

🟢🟢🟢 = Green light blink 3 times, it is "Parameter 3"

Selection mode (Red light)

LED color	Blink times	Mode name	Parameter of mode
Red, Mode 1	🔴	Adjust Brightness	4 Level, High, Middle, Low, ECO, Low
Red, Mode 2	🔴🔴	Adjust Power saving	3 modes, APO Off, APO, Motion detection
Red,, Mode 3	🔴🔴🔴	Exit setting	

Adjust parameter (Green light)

Mode \ Parameter	🟢	🟢🟢	🟢🟢🟢	🟢🟢🟢🟢
Brightness	ECO	Low	Middle	High (default)
Power saving	APO Off No APO, 3D Motion detection	APO On Auto power off, 3D Motion detection (default)	Motion detect Auto power on/ off, Control by 3D Motion detection	-

** 3D Motion detect: if 30 sec no motion that will into sleep mode. If moving that will wake up again.

** APO On (Parameter 2): Auto power off after 30 mins without shot.

** Low Power detection: Lower power automatically turn off to protect battery.

short ⇒ Push and release the power button.

LONG ⇒ Push and hold 5sec. Then release the power button.