


BEGADI Universalmagazine Typ 8, G3 HighCap Modification for Schwaben Arms M41 / CA G3 AEG Series

These magazines cause feeding problems in the Schwaben Arms M41 / CA G3 AEG series.

The reason is that the magazines are not pushed far enough into the magazine well.



To solve the problem, a small piece of metal/plastic (for instance of an old magazine case, PC housing, storage boxes, CD) must be stuck in the mag catch window of the magazine. With hit piece installed, the magazine is pushed further into the magazine well and the feeding problem disappears.