


CNC ALUMINUM HOPUP CHAMBER MI - PRO

3 EXPLODED VIEW



Apply Silicone grease

Apply Lithium grease

Apply Threadlocker

Tighten firmly, do not overtighten

CAUTION: Please check your model carefully before operation!